## Kurzzeit Pistole (ARC) AS 2902

Artikel nr. AS 2902: 198 20 025

Zubehör finden Sie im Zubehörkatalog

Technische Daten	AS 2902
Schweißbereich [Wird primär durch Schweißstromquelle bestimmt]	Ø2-10, Gewindebolzen[PS], Stifte[US], Innengewinde- buchsen[IS], Iso Stifte
Material	Stahl, rostfreier Stahl Ø2-10 Aluminum Sonderbolzen mit Schutzgas Ø2-6
Schweißstromquelle	Trafo / Inverter (ARC)
Schweißzeit	Je nach Gerät 5ms-1000ms
Abhub Einstellungen	0-5mm
Schweißkabelanschluss	50qmm
Steuerkabelanschluss	7pol
Gewicht	0,8kg ohne Kabel
Länge	220mm
Aufnahmedurchmesser Zubehör	Ø32mm
Bolzenhalteraufnahme	Ø10mm
Zubehör	Dreibeinaufsatz, Bolzenhalter3- 8mm, Steckschlüssel



#### Bolzenschweißen mit dem Kurzzeit-Hubzündungs Verfahren

Diese Pistole kann mit allen Bolzenschweißgeräten für die Hubzündung eingesetzt werden. Sie eignet sich besonders für das Verschweißen von Stahl und Edelstahl. Zum Einsatz kommt das Verfahren vorwiegend bei gewölbten oder unebenen Oberflächen. Für die Schutzgasfunktion muss das Schweißgerät entsprechend ausgerüstet sein.





7-poliger Steuerkabelanschluss

robuste 50 qmm Schweißkabel-

Schweißkabel 6,5m

kupplung

Bestellhotline: +49 2302 95640-0

### AS 2902 geeignet für:

2104 2108 2118 2210

# short cycle gun (ARC) AS 2902

articel no. AS 2902: 198 20 025

equipment you can find in the associated prospect

technical data	AS 2902
welding range [depending on studwelder]	Ø2-10 un-/ threaded studs, isolation pins, internal threaded (tapped) studs
material	steel, stainless steel Ø2-10 aluminium Ø2-6 with gas and special studs brass Ø2-8
suitable power source	transformer / Inverter (ARC)
welding time	depending on studwelder 5ms-1000ms
welding gap adjustment	0-5mm
weld cable plug	50qmm
control cable plug	7pol
weight	0,8kg (without cable)
length	220mm
diameter for front tool	Ø32mm
chuck adapter	Ø10mm
equipment	tripod attachment/ chuck 3-8mm / socket wrench



#### **Arc studwelding**

This tried and tested studwelding gun is suitable for all AS ARC studwelding units. Materials as steel, stainless steel and also aluminium can be welded. For welding with shielding gas the studwelder has to be equipped with the shielding gas function.

- 1
- welding on thin work pieces (1/8xD)
- / lov
  - low welding penetration
- 1
  - the lift can be set without tools
- 1
  - 7-pole control cable plug
- 1
- welding cable 6,5m
- 1
- thought 50 qmm welding cable plug

AS 2902 suitable for:

2104

2108

2118

hotline: +49 2302 95640-0

2210